

**Aeronautical Systems Center
Air Force Plant 44
Tucson, Arizona**



Administrative Record Index Part 1 of 4

THIS INDEX INCLUDES ALL DOCUMENTS

01001 THROUGH 02013

Prepared by:

**U.S. Department of the Air Force
Aeronautical Systems Center
Acquisition Environmental, Safety and Health Division (ASC/ENVR)
Wright-Patterson AFB, Ohio**

UPDATED September 2006

**ASC/ENVR
Wright-Patterson AFB, Ohio
1-800-982-7248, extension 53417**

DOCNO	CATEGORY	TITLE	AUTHOR	PAGE	DATE
1001	1.04	Phase I Investigation of Subsurface Conditions in the Vicinity of Abandoned Waste Disposal Sites, Hughes Aircraft Company Manufacturing Facility, Tucson, Arizona, Volume I	Hargis & Montgomery, Inc.	302	1/15/1982
1001	1.04	Phase I investigation of Subsurface Conditions in the Vicinity of Abandoned Waste Disposal Sites Hughes Aircraft Company Manufacturing Facility; Tucson, Arizona, Volume II (Illustrations)	Hargis & Montgomery, Inc.	2	1/15/1982
1001	1.04	Phase I Investigation of Subsurface Conditions In The Vicinity of Abandoned Waste Disposal Sites, Hughes Aircraft Manufacturing Facility, tucson, Arizona, Volume III (Appendices)	Hargis & Montgomery, Inc.	229	1/15/1982
1002	1.04	Installation Restoration Program Phase I - Records Search, Air Force Plant 44	Science Application International Corporation	260	10/31/1985
1004	1.02	Site Inspection US Air Force Plant 44	Hargis & Associates	123	7/20/1989
1005	1.04	Evaluation of Data Collected by Tucson Groundwater Contamination Study Task Force in the vicinity of U.S. Air Force Plant No. 44, Tucson, Arizona	Hargis & Montgomery, Inc.	97	2/4/1983
1011	1.07	Installation Restoration Program Stage 1 for Air Force Plant 44, Tucson, AZ, Quality Assurance Project Plan	Earth Technology Corporation	145	2/28/1991
1012	1.08	Installation Restoration Program Stage 1 Health & Safety Plan for Air Force Plant 44, Tucson, AZ	Earth Technology Corporation	103	2/28/1991
1013	1.04	Installation Restoration Program Stage 1, Air Force Plant 44, Tucson, AZ, Review of Aerial Photographs	Earth Technology corporation	141	11/30/1989
1014	1.04	As-Built Report: Construction of 13-RCRA Monitor Wells and Four Perched Zone Monitor Wells	Groundwater Resources Consultants, Inc.	84	11/9/1990
1015	1.04	Field Operation Procedures (Soil Gas), Air Force Plant No. 44, Tucson, AZ	Tracer Research Corporation (for Earth Technology Corp)	23	
1019	1.04	Annual Summary of Wellfield Reclamation Operations and Changes in Groundwater Conditions, April 1987 through March 1989, Air Force Plant No. 44	Groundwater Resources Consultants, Inc.	454	7/14/1989
1023	1.05	Characterization of Site Hydrogeology in the Vicinity of the Surface Impoundments at U.S. Air Force Plant No. 44, Tucson, AZ, Volume I	Groundwater Resources Consultants, Inc.	17	2/6/1991
1024	1.05	Characterization of Site Hydrogeology in the Vicinity of the Surface Impoundments at U.S. Air Force Plant No. 44, Tucson, AZ, Volume II (Illustrations)	Groundwater Resources Consultants, Inc.	17	2/6/1991
1028	1.04	Summary of 1986 Hydrologic Monitoring Program (2 Volumes), U.S. Air Force Plant No. 44, Tucson, Arizona. Volume I Includes Text, Tables, Illustrations and Appendices A & B. Volume II Includes Appendices C through G	Hargis & Associates, Inc.	522	6/2/1987
1028	1.04	Summary of 1986 Hydrologic Monitoring Program; Air Force Plant 44, Tucson, Arizona (Volume I)	Hargis & Associates, Inc.	192	6/2/1987
1029	1.05	Submittal of Basic Data, Hydrogeologic and Water Quality Conditions and Selected Monitor Well Data in the Vicinity of the Hughes Aircraft Company Surface Impoundments	Groundwater Resources Consultants, Inc.	114	7/29/1987
1030	1.07	Installation Restoration Program, RCRA Facility Investigation for Air Force Plant 44, Draft Quality Assurance Project Plan	The Earth Technology Corporation	170	2/28/1989
1031	1.08	Installation Restoration Program, RCRA Facility Investigation for air Force Plant 44, Tucson, Arizona, Draft Health & Safety Plan	The Earth Technology Corporation	95	2/28/1989

DOCNO	CATEGORY	TITLE	AUTHOR	PAGE	DATE
1033	1.04	Phase II Investigation of Subsurface Conditions In The Vicinity of Abandoned Waste Disposal Sites, Hughes Aircraft Company Manufacturing Facility Tucson, Airizona; Volume I	Hargis & Montgomery Inc.	327	3/12/1982
1033	1.04	Phase II Investigation of Subsurface Conditions In The Vicinity of Abandoned Waste Disposal Sites, Hughes Aircraft Company Manufacturing Facility Tucson, Airizona; Volume II	Hargis & Montgomery Inc.	327	3/12/1982
1033	1.04	Phase II Investigation of Subsurface Conditions In The Vicinity of Abandoned Waste Disposal Sites, Hughes Aircraft Company Manufacturing Facility Tucson, Airizona; Volume III	Hargis & Montgomery Inc.	327	3/12/1982
1034	1.03	RCRA Facility Assessment, Hughes Aircraft Corporation, U.S. Air Force Plant No. 44 Tucson, Arizona	United States Environmental	249	2/5/1988
1035	1.04	Summary of 1985 Hydrologic Monitoring Program, U.S. Air Force Plant No. 44 Tucson, Arizona, Volume I, Appendices A-C	Hargis & Associates, Inc.	252	8/29/1986
1036	1.07	Quality Assurance Plan Reclamation Wellfield Drilling Construction, Testing and Sampling, at U.S. Air Force Plant 44, Tucson, Arizona	Hargis and Associates, Inc.	56	5/19/1986
1038	1.04	Hughes Aircraft Company Groundwater Treatment Facility and Reclamation and Recharge Well Fields	Metcalf and Eddy	569	12/12/1985
1039	1.04	Design Analysis for Groundwater Treatment Facility for Hughes Aircraft Company at Air Force Plant 44, Tucson Arizona	Metcalf and Eddy	625	12/12/1985
1040	1.04	Analysis of Data Collected by Tucson Groundwater Contamination Study Task Force in the Vicinity of Tucson International Airport, Tucson, Arizona; Volume II, Appendices	Hargis and Montgomery, Inc.	288	6/22/1984
1041	1.03	Preliminary Reclamation Wellfield Design and Assessment of Water Treatment Alternatives, U.S. Air Force Plant 44, Tucson, Arizona	Hargis and Montgomery, Inc.	33	8/9/1982
1042	1.04	Analysis of Data Collected by Tucson Groundwater Assessment of Water Treatment Alternatives, U.S Air Force Plant 44, Tucson, Arizona	Hargis and Montgomery, Inc.	54	6/22/1984
1043	1.04	Design of Reclamation Wellfield, U.S. Air Force Plant 44, Tucson, Arizona	Hargis and Associates, Inc.	30	3/15/1985
1044	1.04	Recommendation for Pilot Reclamation System, U.S. Air Force Plant 44, Tucson, Arizona	Hargis and Montgomery, Inc.	12	5/30/1984
1045	1.02	Site Inspection U.S. Air force Plant 44, Tucson Arizona	Hargis and Associates, Inc.	89	11/15/1989
1046	1.04	Perched Zone Monitoring System - Data - Results, U.S. Air Force Plant 44, Tucson, Arizona	Hargis and Associates, Inc.	76	6/2/1987
1047	1.04	Interim Emergency Measures Cementing of Wells HAC-1, HAC-2, AND HAC-4; U.S. Air Force Plant 44	Hargis and Associates, Inc.	21	5/25/1983
1048	1.04	Evaluation of Water Use Alternatives Proposed Reclamation Wellfield, U.S. Air Force Plant 44	Hargis and Associates, Inc.	21	10/11/1984
1049	1.04	Construction of Recharge Well R-17, U.S. Air Force Plant 44, Tucson, Arizona	Hargis and Associates, Inc.	32	2/20/1986

DOCNO	CATEGORY	TITLE	AUTHOR	PAGE	DATE
1050	1.04	Construction of Perched Zone Monitoring Wells S-1 through S-19, U.S. Air Force Plant 44, Tucson, Arizona	Hargis and Associates Inc.	55	11/2/1984
1051	1.04	Annual Groundwater Reclamation Project Reports, U.S. Air Force Plant 44 April 1992 through December 1992	Groundwater Recourses	436	1/19/1993
1052	1.04	Annual Groundwater Reclamation Project Reports, U.S. Air force Plant 44, April 1991 through March 1992	Groundwater Resources	416	4/20/1992
1053	1.04	Annual Groundwater Reclamation Report, U.S. Air Force Plant 44, April 1987 through March 1988	Groundwater Resources Consultants, Inc.	406	8/12/1988
1054	1.04	Annual Groundwater Reclamation Report, U.S. Air Force Plant 44, April 1988 through March 1989	Groundwater Resources Consultants, Inc.	432	7/14/1989
1055	1.04	Annual Groundwater Reclamation Report, U.S. Air Force Plant 44, April 1989 through March 1990	Groundwater Resources Consultants, Inc.	362	7/13/1990
1056	1.04	Annual Groundwater Reclamation Project Reports; U.S. Air Force Plant 44, April 1990 through March 1991	Groundwater Resources Consultants, Inc.	422	6/20/1991
1057	1.04	Summary of 1983 Hydrologic Monitoring Program; U.S. Air Force Plant No. 44; Tucson, Arizona; Volume I	Hargis and Montgomery, Inc.	44	6/22/1984
1058	1.04	Summary of 1983 Hydrologic Monitoring Program; U.S. Air Force Plant No. 44; Tucson, Arizona; Volume II	Hargis and Montgomery, Inc.	368	6/22/1984
1059	1.04	Summary of 1982 Hydrologic Monitoring Program; U.S. Air Force Plant No. 44; Tucson, Arizona; Volume I	Hargis and Montgomery, Inc.	308	7/15/1983
1060	1.04	Summary of 1982 Hydrologic Monitoring Program; U.S. Air Force Plant No. 44; Tucson, Arizona; Volume II, Illustrations	Hargis and Montgomery, Inc.	2	7/15/1983
1061	1.04	North Capture Zone Assessment, USAF Plant 44	Ground-Water Resources Consultants	112	8/14/1989
1062	1.04	Tucson International Airport Soils Investigation	Hargis and Associates, Inc.	63	11/5/1986
1065	1.08	Installation Restoration Program (IRP) Stage I, Health and Safety Plan; Air Force Plant 44, Tucson, Arizona	The Earth Technology Corporation	120	1/31/1994
1066	1.07	Installation Restoration Program Stage I; Quality Assurance Project Plan; Air Force Plant 44, Tucson, Arizona	The Earth Technology Corporation	135	1/31/1995
1067	1.07	Installation Restoration Program Stage I, Quality Assurance Project Plan; Air Force Plant 44, Tucson, Arizona	The Earth Technology Corporation	133	5/30/1992
1068	1.08	Installation Restoration Program (IRP) Treatability Studies, Health and Safety Plan; Air Force Plant 44, Tucson, Arizona	The Earth Technology Corporation	78	8/30/1992
1069	1.08	Installation Restoration program 9IRP), Health and Safety Plan for Air Force Plant 44 Removal Actions, Final; Air Force Plant 44, Tucson International Airport Area Superfund Site, Tucson, Arizona	Earth Tech	79	12/31/1995
1070	1.09	Installation Restoration Program 9IRP), Operation and Maintenance Manual for Soil Vapor Extraction System, Interim Final; Air Force Plant 44, Tucson International Airport Area Superfund Site, Tucson, Arizona	Earth Tech	35	12/31/1995
1071	1.07	Installation Restoration Program (IRP), Quality Assurance Project Plan, Final; Air Force Plant 44, Tucson Internaitonal Airport Area Superfund Site, Tucson Arizona	Earth Tech	139	12/31/1995

DOCNO	CATEGORY	TITLE	AUTHOR	PAGE	DATE
1072	1.05	Evaluation of Hughes Aircraft, U.S. Air Force Plant No. 44 Tucson, Arizona	U.S. EPA	81	4/30/1988
1073	1.05	Digital Simulation of Containment transport in the Regional Aquifer System, U.S. Air Force Plant No.44, Tucson, Arizona	Hargis & Montgomery, Inc.	74	10/11/1982
1074	1.05	Work Plan for Construction and Pilot Testing of Two Vertical Circulation Wells at U.S. Air Force Plant 44, Pima County, Arizona	Errol L. Montgomery &	219	6/5/1998
1075	1.04	Installation of Groundwater Monitor Wells M-77 through M-80, Vapor Extraction Wells VE-306 through VE-308, and Vapor Monitor Wells VM-1401 and VM-1402	Groundwater Resources Consultants, Inc.	93	4/24/1998
1076	1.04	Supplemental Investigation Report for Activities West of IRP Site 5 Draft	Earth Tech	128	4/30/1998
1077	1.04	Evaluation of Shallow Groundwater Zone Bio-Remediation Project, USAF Plant 44	Errol L. Montgomery &	91	12/10/1998
2001	2.01	Installation Restoration Program (IRP) Stage 1, Removal Action Work Plan IRP Sites 4 and 5, and Site 6 "Hotspots", Final; Air Force Plant 44, Tucson, Arizona	Earth Tech	30	10/31/1995
2002	2.03	Proposed Plan and Engineering Evaluation Cost Analysis Sites, 1,2,3,4 and 5 Responsiveness Summary at Air Force Plant 44, Tucson International Airport Area Superfund Site, Tucson, Arizona	Earth Tech	29	11/30/1995
2003	2.01	Installation Restoration Program (IRP) Proposed Plan For Soil Clean Up Final; Air Force Plant 44, Tucson International Airport Area Superfund Site, Tucson Arizona	Earth Tech	56	11/30/1995
2004	2.03	Installation Restoration Program (IRP) Engineering Evaluation/Cost Analysis Overall Final; Air Force Plant 44, Tucson International Airport Area Superfund Site, Tucson, Arizona	Earth Tech	69	11/30/1995
2005	2.03	Installation Restoration Program (IRP) Engineering Evaluation/Cost Analysis, Site 5 Former Sludge Drying Beds Final; Air Force Plant 44, Tucson International Airport Area Superfund Site, Tucson, Arizona	Earth Tech	18	11/30/1995
2006	2.03	Installation Restoration Program (IRP) Engineering Evaluation/Cost Analysis, Site 4, Former Unlined Surface Impoundments Final; Air Force Plant 44, Tucson International Airport Area Superfund Site, Tucson, Arizona	Earth Tech	18	11/30/1995
2007	2.03	Installation Restoration Program (IRP), Engineering Evaluation/Cost Analysis, site 3, Inactive Drainage Channel Disposal Pits, Final; Air Force Plant 44, Tucson International Airport Area Superfund site, Tucson, Arizona	Earth Tech	21	11/30/1995
2008	2.03	Installation Restoration Program (IRP), Engineering Evaluation/Cost Analysis, site 2, FACO Landfill, Final; Air Force Plant 44, Tucson International Airport Area Superfund Site, Tucson, Arizona	Earth Tech	21	11/30/1995
2009	2.03	Installation Restoration Program (IRP), Engineering Evaluation/Cost Analysis, Site 1 Ranch Site, Final; Air Force Plant 44, Tucson International Airport Area Superfund Site, Tucson, Arizona	Earth Tech	19	11/30/1995

DOCNO	CATEGORY	TITLE	AUTHOR	PAGE	DATE
2010	2.01	Installation Restoration Program (IRP), Sites 1,2, and 3 Non-Time Critical Removal Action Work Plan, Final; Air Force Plant 44, Tucson International Airport Area Superfund Site, Tucson, Arizona	Earth tech	86	12/31/1995
2011	2.01	Final Report, Implementaiton Work Plan, Shallow Groundwater Zone Removal Action; Air Force Plant 44, Tucson, Arizona	Woodward-Clyde Consultants	179	4/30/1996
2012	2.01	Shallow Groundwater Zone Removal Action Engineering Specifications; Air Force Plant 44, Hughes Missile Systems Company, Tucson, Arizona	Hargis + Associates, Inc.	317	8/30/1996
2013	2.01	Shallow Groundwater Zone Removal Action Wells Engineering Specifications; Air Force Plant 44 Hughes Missile Systems company, Tucson, Arizona	Hargis + Associates, Inc.	77	8/30/1996